





are minimum and maximum temperatures recorded by the drag marker. The included magnet serves to reset the marker in any chosen time interval.

One support helps to install the classic "window sill thermometer". It works reliably and maintenance free over a long period.

- simple measuring principle
- easy and unambiguously to read scale at a weather proof scale
- small, compact, practical
- field proven

universally applicable air temperature thermometer



Standard Line	(1014)	Six Thermometer	ld-No. 00.10140.000 000
Measuring element:		liquid expansion thermometer with drag mar	ker
Measuring-/ Application range:		-30+50 ℃	
Accuracy:		below o °C: $\pm$ 1.5 °C • above o °C: $\pm$ 1.0 °C	
Resolution/ Scale:		$\leq$ 1 °C/ 1 °C	
Dimensions:		230 x 70 x 30 mm	
Weight:		o.3 kg	
Included in delivery:		1 magnet	

